

INTRODUCTION	4-9	Safety on Band Saws	43
SAFEGUARDING	10-61	Safety on Disc/Belt Sanders	44
Electrically Interlocked Heavy-Duty Shields	10-15	Safety on Table Saws	45
Electrically Interlocked Drill Press Shields	10-11	All-Purpose Shields	46-61
Electrically Interlocked Lathe Chuck Shields	12	Adjustable Slide Shields	46
Electrically Interlocked Crossslide/Carriage Travel Lathe Shields	13	Rigid-Arm Magnetic-Base Shields	47
Electrically Interlocked Milling Machine Shields	14-15	Universal Ball & Socket Shields	48-50
Safety on Drill Presses	16-21	Flexible Copolymer Lock-Arm Shields	51-54
Safety Chip Shields	18	Flexible Spring-Steel Arm Shields	55-58
Heavy-Duty Aluminum Drill Press Shields	19	On/Off Magnetic-Base Shields	59-60
Telescoping Drill Press Shields	20-21	Free-Standing Shield Assembly	61
Spring-Loaded/Self-Ejecting Chuck Keys for Drill Presses	21	FLEXIBLE-ARM LAMPS	62
Safety on Lathes	22-31	DISCONNECT SWITCHES, MOTOR STARTERS, AND ACCESSORIES	63-69
Sliding Lathe Shields	24	Lockouts	63
Crossslide-Travel Lathe Shields	25	Tagouts	63
Small Steel Lathe Chuck Shields	26	Lockout Valves	64
Large Steel Lathe Chuck Shields	27	Single-Phase Disconnect/Starter	64
Transparent Lathe Chuck Shields	28	Sensing Saf-Start® Packages	65
Mounting Brackets	29	Enclosed Transformers	66
Lathe Chuck Wrenches	30-31	IEC Fused Disconnect Switches, Magnetic Motor Starters, and Combinations	66
Safety on Milling Machines	32-38	Disconnect and Starter Part Numbering System Chart	67
Chip Shields for Bridgeport Mills	34-35	Remote Operator Station Part Numbering System Chart	68
Bridgeport Vertical Mill Controls	35	Remote Stations	69
Slide and Swing-Aside Shields	36-37	DANGER SIGNS AND LABELS	70-71
Rear Shield Assemblies	37	SURVEY FOR CUTTING AND TURNING MACHINES	72-73
Milling Machine Belt Covers	38	OSHA STANDARDS	74
Electrical Interlock Assembly	38	MACHINE SAFEGUARDING SEMINAR	75-79
Safety on Bench Grinders	39-42	INDEX	80-81
Double-Wheel Grinder Shields	40	TERMS & CONDITIONS OF SALE	82
Single-Wheel Grinder Shields	40		
Pivot-Mount Grinder Shields	41		
Standard-Mount Grinder Shields	41		
Bench Grinder Safety Gauge	42		

The applications described in this catalog are for instructional and informational purposes only; the photos in this catalog are for illustrative purposes only. They may not represent actual usage. This catalog has been carefully checked for accuracy and is thought to be fully consistent with the products described herein. However, Rockford Systems, Inc. does not assume liability for the contents of this publication or for the use of any products described herein. Rockford Systems, Inc. reserves the right to make changes to the products and documentation without further notice.

This document contains proprietary information protected by copyright. No part of this catalog may be reproduced, transmitted, stored in a retrieval system, or translated into any language, in any form or by any means without prior written permission from Rockford Systems, Inc., P.O. Box 5525, Rockford, Illinois 61125-0525. Rockford Systems reserves the right to make changes or revisions to the material contained in this catalog and cannot be held liable for incidental or consequential damages resulting from the furnishing, performance or use of this material.